





Microsemi

BR246-320A2-28V-024L


| | |
|---------------------|---|
| Tau Wae: | BR246-320A2-28V-024L |
| Kaihanga / Waitohu: | Microsemi |
| Whakaahuatanga hua | RELAY |
| Ngā Rauemi: |  BR246-320A2-28V-024L.pdf |
| RoHS Tūnga |  Kei roto nga rangatira / RoHS kaore i te ture |
| Waeheere Stock | 5519 pcs stock |
| Tuhinga mai i | Hong Kong |
| Te Ara Tuhi | DHL/Fedex/TNT/UPS/EMS |



TONO MO TE WHAKAHUA

Ko te whakaahua he tohu. Tirohia nga korero mo nga taipitopito hua.













Ngā whakaaturanga o BR246-320A2-28V-024L

| | |
|---|--|
| TAU WAE | BR246-320A2-28V-024L |
| KAIHANGA | Microsemi |
| WHAKAAHUATANGA | RELAY |
| WHAKAHAERE TOKO WHAKAHAERE / ROHS TŪNGA | Kei roto nga rangatira / RoHS kaore i te ture |
| HE RAHINGA KEI TE WĀTEA | 5519 pcs |
| PEPA RARAUNGA |  BR246-320A2-28V-024L.pdf |
| RAUPAPA | * |
| TAUMATA WHAKAARO MOE (MSL) | 1 (Unlimited) |
| WHAKAHAERE TOKO WHAKAHAERE / ROHS TŪNGA | Contains lead / RoHS non-compliant |
| WHAKAAHUATANGA TAIPITOPITO | Relay Coil |

Ngā tūtohu e hāngai ana

| | | |
|---|--|--|
| Microsemi BR246-320A2-28V-024L | BR246-320A2-28V-024L Kaiwhiwhi | BR246-320A2-28V-024L Kaiwhakarato |
| BR246-320A2-28V-024L Utu | BR246-320A2-28V-024L Pikitia | BR246-320A2-28V-024L Whakaahua |
| BR246-320A2-28V-024L PDF Datasheet | BR246-320A2-28V-024L Download Datasheet | Tuhinga BR246-320A2-28V-024L |
| BR246-320A2-28V-024L Stock | Hokona BR246-320A2-28V-024L | Hokona Microsemi BR246-320A2-28V-024L |
| Microsemi BR246-320A2-28V-024L | Microsemi Kaiwhakarato | Microsemi Kaiwhiwhi |
| Microsemi BR246-320A2-28V-024L | Microsemi Analog Mixed Signal Group BR246-320A2-28V-024L | Microsemi Analog Mixed Signal Group [MIL] BR246-320A2-28V-024L |
| Microsemi Consumer Medical Product Group BR246-320A2-28V-024L | Microsemi HI-REL [MIL] BR246-320A2-28V-024L | Microsemi Power Management Group BR246-320A2-28V-024L |
| Microsemi Power Products Group BR246-320A2-28V-024L | Microsemi SoC BR246-320A2-28V-024L | Microsemi Commercial Components Group BR246-320A2-28V-024L |
| Microsemi Corporation BR246-320A2-28V-024L | Microsemi Solutions Sdn Bhd. BR246-320A2-28V-024L | |

Ngā Hua e hāngai ana

| | |
|---|---|
|  <p>BR246-320A2-28V-024M Kaihanga: Microsemi Whakaahuatanga: RELAY GEN PURPOSE DPDT 10A 28V I roto i te taonga: 5333 pcs</p> <p>RFQ</p> |  <p>BR246-320B1-28V-020L Kaihanga: Microsemi Whakaahuatanga: RELAY I roto i te taonga: 5032 pcs</p> <p>RFQ</p> |
|  <p>BR246-320B1-28V-020M Kaihanga: Microsemi Whakaahuatanga: RELAY I roto i te taonga: 5940 pcs</p> <p>RFQ</p> |  <p>BR246-320A2-28V-010 Kaihanga: Microsemi Whakaahuatanga: RELAY I roto i te taonga: 3528 pcs</p> <p>RFQ</p> |
|  <p>BR246-320A1-28V-021M Kaihanga: Microsemi Whakaahuatanga: RELAY I roto i te taonga: 6351 pcs</p> <p>RFQ</p> |  <p>BR246-20G3-6V-009L Kaihanga: Microsemi Whakaahuatanga: RELAY I roto i te taonga: 4935 pcs</p> <p>RFQ</p> |
|  <p>BR246-320A2-28V-029M Kaihanga: Microsemi Whakaahuatanga: RELAY I roto i te taonga: 4180 pcs</p> <p>RFQ</p> |  <p>BR246-320A2-28V Kaihanga: Microsemi Whakaahuatanga: RELAY I roto i te taonga: 4259 pcs</p> <p>RFQ</p> |
|  <p>BR246-320B1-28V Kaihanga: Microsemi Whakaahuatanga: RELAY I roto i te taonga: 5909 pcs</p> <p>RFQ</p> |  <p>BR246-320A1-28V-021L Kaihanga: Microsemi Whakaahuatanga: RELAY I roto i te taonga: 5704 pcs</p> <p>RFQ</p> |
|  <p>BR246-320A2-28V-029L Kaihanga: Microsemi Whakaahuatanga: RELAY I roto i te taonga: 6999 pcs</p> <p>RFQ</p> |  <p>BR246-20G3-6V-009M Kaihanga: Microsemi Whakaahuatanga: RELAY I roto i te taonga: 6267 pcs</p> <p>RFQ</p> |

