

Leader Tech Inc.

48-CBSA-1.0X2.0X0.4

| | |
|---------------------|----------------------------------|
| Tau Wae: | 48-CBSA-1.0X2.0X0.4 |
| Kaihanga / Waitohu: | Leader Tech Inc. |
| Whakaahuatanga hua | 48-CBSA-1.0X2.0X0.4--48S05--CIRC |
| Ngā Rauemi: | 48-CBSA-1.0X2.0X0.4.pdf |
| Waehere Stock | 10924 pcs stock |
| Tuhinga mai i | Hong Kong |
| Te Ara Tuhi | DHL/Fedex/TNT/UPS/EMS |

TONO MO TE WHAKAHUA

Ko te whakaahua he tohu. Tirohia nga korero mo nga taipitopito hua.

Ngā whakaaturanga o 48-CBSA-1.0X2.0X0.4

| | |
|---|--|
| TAU WAE | 48-CBSA-1.0X2.0X0.4 |
| KAIHANGA | Leader Tech Inc. |
| WHAKAAHUATANGA | 48-CBSA-1.0X2.0X0.4--48S05--CIRC |
| WHAKAHAERE TOKO WHAKAHAERE / ROHS TŪNGA | |
| HE RAHINGA KEI TE WĀTEA | 10924 pcs |
| PEPA RARAUNGA | 48-CBSA-1.0X2.0X0.4.pdf |
| WHĀNUI - WHĀNUI | 1.000" (25.40mm) |
| TUHINGA O MUA | Vent Holes in Pattern |
| MOMO | Shield, 2-Piece |
| RAUPAPA | 40-CBS |
| MOMO TAE | Through Hole |
| TE ROA - WHĀNUI | 2.000" (50.80mm) |
| TEITEI - WHĀNUI | 0.400" (10.16mm) |
| WHAKAAHUATANGA TAIPITOPITO | RF Shield Shield, 2-Piece 1.000" (25.40mm) X 2.000" (50.80mm) Vent Holes in Pattern Through Hole |

Ngā tūtohu e hāngai ana

| | | |
|--------------------------------------|--|---|
| Leader Tech Inc. 48-CBSA-1.0X2.0X0.4 | 48-CBSA-1.0X2.0X0.4 Kaiwhiwhi | 48-CBSA-1.0X2.0X0.4 Kaiwhakarato |
| 48-CBSA-1.0X2.0X0.4 Utu | 48-CBSA-1.0X2.0X0.4 Pikitia | 48-CBSA-1.0X2.0X0.4 Whakaahua |
| 48-CBSA-1.0X2.0X0.4 PDF Datasheet | 48-CBSA-1.0X2.0X0.4 Download Datasheet | Tuhinga 48-CBSA-1.0X2.0X0.4 |
| 48-CBSA-1.0X2.0X0.4 Stock | Hokona 48-CBSA-1.0X2.0X0.4 | Hokona Leader Tech Inc. 48-CBSA-1.0X2.0X0.4 |
| Leader Tech Inc. 48-CBSA-1.0X2.0X0.4 | Leader Tech Inc. Kaiwhakarato | Leader Tech Inc. Kaiwhiwhi |
| Leader Tech Inc. 48-CBSA-1.0X2.0X0.4 | | |

Ngā Hua e hāngai ana

| | |
|---|--|
| <p>48-CBSA-1.0X1.0X0.4 Kaihanga: Leader Tech Inc. Whakaahuatanga: 48 SERIES CBS SHIELD ASSEMBLY I roto i te taonga: 6300 pcs</p> <p style="text-align: center; background-color: #ccc; padding: 5px; width: fit-content; margin: 0 auto;">RFQ</p> | <p>48-CBSA-1.0X1.25X0.4 Kaihanga: Leader Tech Inc. Whakaahuatanga: 48 SERIES CBS SHIELD ASSEMBLY I roto i te taonga: 5727 pcs</p> <p style="text-align: center; background-color: #ccc; padding: 5px; width: fit-content; margin: 0 auto;">RFQ</p> |
| <p>48-CBSA-1.0X3.25X0.4 Kaihanga: Leader Tech Inc. Whakaahuatanga: 48 SERIES CBS SHIELD ASSEMBLY I roto i te taonga: 5263 pcs</p> <p style="text-align: center; background-color: #ccc; padding: 5px; width: fit-content; margin: 0 auto;">RFQ</p> | <p>48-CBSA-1.0X3.5X0.4 Kaihanga: Leader Tech Inc. Whakaahuatanga: 48 SERIES CBS SHIELD ASSEMBLY I roto i te taonga: 5589 pcs</p> <p style="text-align: center; background-color: #ccc; padding: 5px; width: fit-content; margin: 0 auto;">RFQ</p> |
| <p>48-CBSA-1.0X2.5X0.4 Kaihanga: Leader Tech Inc. Whakaahuatanga: 48 SERIES CBS SHIELD ASSEMBLY I roto i te taonga: 5666 pcs</p> <p style="text-align: center; background-color: #ccc; padding: 5px; width: fit-content; margin: 0 auto;">RFQ</p> | <p>48-CBSA-0.75X5.75X0.4 Kaihanga: Leader Tech Inc. Whakaahuatanga: 48 SERIES CBS SHIELD ASSEMBLY I roto i te taonga: 3682 pcs</p> <p style="text-align: center; background-color: #ccc; padding: 5px; width: fit-content; margin: 0 auto;">RFQ</p> |
| <p>48-CBSA-1.0X3.0X0.4 Kaihanga: Leader Tech Inc. Whakaahuatanga: 48 SERIES CBS SHIELD ASSEMBLY I roto i te taonga: 5466 pcs</p> <p style="text-align: center; background-color: #ccc; padding: 5px; width: fit-content; margin: 0 auto;">RFQ</p> | <p>48-CBSA-1.0X1.75X0.4 Kaihanga: Leader Tech Inc. Whakaahuatanga: 48 SERIES CBS SHIELD ASSEMBLY I roto i te taonga: 5446 pcs</p> <p style="text-align: center; background-color: #ccc; padding: 5px; width: fit-content; margin: 0 auto;">RFQ</p> |
| <p>48-CBSA-0.75X6.0X0.4 Kaihanga: Leader Tech Inc. Whakaahuatanga: 48 SERIES CBS SHIELD ASSEMBLY I roto i te taonga: 4101 pcs</p> <p style="text-align: center; background-color: #ccc; padding: 5px; width: fit-content; margin: 0 auto;">RFQ</p> | <p>48-CBSA-1.0X1.5X0.4 Kaihanga: Leader Tech Inc. Whakaahuatanga: 48 SERIES CBS SHIELD ASSEMBLY I roto i te taonga: 5716 pcs</p> <p style="text-align: center; background-color: #ccc; padding: 5px; width: fit-content; margin: 0 auto;">RFQ</p> |
| <p>48-CBSA-1.0X2.75X0.4 Kaihanga: Leader Tech Inc. Whakaahuatanga: 48 SERIES CBS SHIELD ASSEMBLY I roto i te taonga: 5087 pcs</p> <p style="text-align: center; background-color: #ccc; padding: 5px; width: fit-content; margin: 0 auto;">RFQ</p> | <p>48-CBSA-1.0X2.25X0.4 Kaihanga: Leader Tech Inc. Whakaahuatanga: 48 SERIES CBS SHIELD ASSEMBLY I roto i te taonga: 5140 pcs</p> <p style="text-align: center; background-color: #ccc; padding: 5px; width: fit-content; margin: 0 auto;">RFQ</p> |