



MaxBotix Inc.

## MB7360-100

Tau Wae:

MB7360-100

Kaihanga / Waitohu:

MaxBotix Inc.

Whakaahuatanga hua

ULTRASONIC SENSOR HRXL-MAXSONAR

Ngā Rauemi:

MB7360-100.pdf

RoHS Tūnga

RoHS Compliant

Waehere Stock

899 pcs stock

Tuhinga mai i

Hong Kong

Te Ara Tuhi

DHL/Fedex/TNT/UPS/EMS

**TONO MO TE WHAKAHUA**

Ko te whakaahua he tohu. Tirohia nga korero mo nga taipitopito hua.

### Ngā whakaaturanga o MB7360-100

TAU WAE	MB7360-100
KAIHANGA	MaxBotix Inc.
WHAKAAHUATANGA	ULTRASONIC SENSOR HRXL-MAXSONAR
WHAKAHAERE TOKO WHAKAHAERE / ROHS TŪNGA	RoHS Compliant
HE RAHINGA KEI TE WĀTEA	899 pcs
PEPA RARAUNGA	MB7360-100.pdf
PUTANGA - KUA TOHUA	2.8 V ~ 5.5 V
RAUPAPA	HRXL-MaxSonar-WR
ROHS TŪNGA	RoHS Compliant
PACKAGING	Bulk
ĒTAHI INGOA	1863-1023
TAE MAHI	-40°C ~ 65°C (TA)
RAUTANGA	42kHz
WHAKAAHUATANGA TAIPITOPITO	Ultrasonic Sensor 42kHz
TE PEE MAAMA	11°

### Ngā tūtohu e hāngai ana

MaxBotix Inc. MB7360-100	MB7360-100 Kaiwhiwhi	MB7360-100 Kaiwhakarato
MB7360-100 Utu	MB7360-100 Pikitia	MB7360-100 Whakaahua
MB7360-100 PDF Datasheet	MB7360-100 Download Datasheet	Tuhinga MB7360-100
MB7360-100 Stock	Hokona MB7360-100	Hokona MaxBotix Inc. MB7360-100
MaxBotix Inc. MB7360-100	MaxBotix Inc. Kaiwhakarato	MaxBotix Inc. Kaiwhiwhi
MaxBotix Inc. MB7360-100		

### Ngā Hua e hāngai ana

<p><b>MB7354-821</b> Kaihanga: MaxBotix Inc. Whakaahuatanga: ULTRASONIC SENSOR HRXL-MAXSONAR I roto i te taonga: 317 pcs</p> <p><b>RFQ</b></p>	<p><b>MB7360-121</b> Kaihanga: MaxBotix Inc. Whakaahuatanga: ULTRASONIC SENSOR HRXL-MAXSONAR I roto i te taonga: 400 pcs</p> <p><b>RFQ</b></p>
<p><b>MB7354-820</b> Kaihanga: MaxBotix Inc. Whakaahuatanga: ULTRASONIC SENSOR HRXL-MAXSONAR I roto i te taonga: 376 pcs</p> <p><b>RFQ</b></p>	<p><b>MB7360-111</b> Kaihanga: MaxBotix Inc. Whakaahuatanga: ULTRASONIC SENSOR HRXL-MAXSONAR I roto i te taonga: 383 pcs</p> <p><b>RFQ</b></p>
<p><b>MB7354-831</b> Kaihanga: MaxBotix Inc. Whakaahuatanga: ULTRASONIC SENSOR HRXL-MAXSONAR I roto i te taonga: 280 pcs</p> <p><b>RFQ</b></p>	<p><b>MB7360-120</b> Kaihanga: MaxBotix Inc. Whakaahuatanga: ULTRASONIC SENSOR HRXL-MAXSONAR I roto i te taonga: 600 pcs</p> <p><b>RFQ</b></p>
<p><b>MB7354-811</b> Kaihanga: MaxBotix Inc. Whakaahuatanga: ULTRASONIC SENSOR HRXL-MAXSONAR I roto i te taonga: 352 pcs</p> <p><b>RFQ</b></p>	<p><b>MB7360-110</b> Kaihanga: MaxBotix Inc. Whakaahuatanga: ULTRASONIC SENSOR HRXL-MAXSONAR I roto i te taonga: 664 pcs</p> <p><b>RFQ</b></p>
<p><b>MB7360-130</b> Kaihanga: MaxBotix Inc. Whakaahuatanga: ULTRASONIC SENSOR HRXL-MAXSONAR I roto i te taonga: 518 pcs</p> <p><b>RFQ</b></p>	<p><b>MB7360-101</b> Kaihanga: MaxBotix Inc. Whakaahuatanga: ULTRASONIC SENSOR HRXL-MAXSONAR I roto i te taonga: 592 pcs</p> <p><b>RFQ</b></p>
<p><b>MB7354-830</b> Kaihanga: MaxBotix Inc. Whakaahuatanga: ULTRASONIC SENSOR HRXL-MAXSONAR I roto i te taonga: 366 pcs</p> <p><b>RFQ</b></p>	<p><b>MB7354-810</b> Kaihanga: MaxBotix Inc. Whakaahuatanga: ULTRASONIC SENSOR HRXL-MAXSONAR I roto i te taonga: 473 pcs</p> <p><b>RFQ</b></p>

