



TDK Corporation

## HHM1596A1

Tau Wae:

HHM1596A1

Kaihanga / Waitohu:

TDK Corporation

Whakaahuatanga hua

BALUN 3.1GHZ-4.9GHZ 50/100 0805

Ngā Rauemi:

HHM1596A1.pdf

RoHS Tūnga

Whakahaerehia te kore utu / RoHS

Waehere Stock

493437 pcs stock

Tuhinga mai i

Hong Kong

Te Ara Tuhi

DHL/Fedex/TNT/UPS/EMS

**TONO MO TE WHAKAHUA**

Ko te whakaahua he tohu. Tirohia nga korero mo nga taipitopito hua.

### Ngā whakaaturanga o HHM1596A1

TAU WAE	HHM1596A1
KAIHANGA	TDK Corporation
WHAKAAHUATANGA	BALUN 3.1GHZ-4.9GHZ 50/100 0805
WHAKAHAERE TOKO WHAKAHAERE / ROHS TŪNGA	Whakahaerehia te kore utu / RoHS
HE RAHINGA KEI TE WĀTEA	493437 pcs
PEPA RARAUNGA	HHM1596A1.pdf
RAUPAPA	HHM
HOKI HOKI (MIN)	10dB
RAWEHANGA PUTANGA	180° ±15°
PACKAGING	Tape & Reel (TR)
PAA / CASE	0805 (2012 Metric)
ĒTAHI INGOA	445-3386-2
MOMO TAE	Surface Mount
TAUMATA WHAKAARO MOE (MSL)	1 (Unlimited)
WHAKAHAERE TOKO WHAKAHAERE / ROHS TŪNGA	Lead free / RoHS Compliant
KO TE WHAKAKORE I TE MAHINGA (MAX)	1.0dB
HAAPAPA - NGA HAUARO / WHAKATIKA	50 / 100 Ohm
MAHINGA RAWE	3.1GHz ~ 4.9GHz
WHAKAAHUATANGA TAIPITOPITO	RF Balun 3.1GHz ~ 4.9GHz 50 / 100 Ohm 0805 (2012 Metric)

### Ngā tūtohu e hāngai ana

TDK Corporation HHM1596A1	HHM1596A1 Kaiwhiwhi	HHM1596A1 Kaiwhakarato
HHM1596A1 Utu	HHM1596A1 Pikitia	HHM1596A1 Whakaahua
HHM1596A1 PDF Datasheet	HHM1596A1 Download Datasheet	Tuhinga HHM1596A1
HHM1596A1 Stock	Hokona HHM1596A1	Hokona TDK Corporation HHM1596A1
TDK Corporation HHM1596A1	TDK Corporation Kaiwhakarato	TDK Corporation Kaiwhiwhi
TDK Corporation HHM1596A1		

### Ngā Hua e hāngai ana

<p><b>HHM1589E1</b> Kaihanga: TDK Corporation Whakaahuatanga: BALUN 350MHZ-470MHZ 50/200 0805 I roto i te taonga: 435579 pcs</p> <p><b>RFQ</b></p>	<p><b>HHM1570B1</b> Kaihanga: TDK Corporation Whakaahuatanga: BALUN 4.9GHZ-5.95GHZ 50/100 0805 I roto i te taonga: 162835 pcs</p> <p><b>RFQ</b></p>
<p><b>HHM1711D1</b> Kaihanga: TDK Corporation Whakaahuatanga: BALUN 2.4GHZ-2.5GHZ 50/100 0603 I roto i te taonga: 180690 pcs</p> <p><b>RFQ</b></p>	<p><b>HHM1595A1</b> Kaihanga: TDK Corporation Whakaahuatanga: BALUN 3GHZ-8GHZ 50/100 0805 I roto i te taonga: 163352 pcs</p> <p><b>RFQ</b></p>
<p><b>HHM1591D1</b> Kaihanga: TDK Corporation Whakaahuatanga: BALUN 350MHZ-470MHZ 50/100 0805 I roto i te taonga: 466597 pcs</p> <p><b>RFQ</b></p>	<p><b>HHM1583B1</b> Kaihanga: TDK Corporation Whakaahuatanga: BALUN 3.1GHZ-4.9GHZ 50/100 0805 I roto i te taonga: 404898 pcs</p> <p><b>RFQ</b></p>
<p><b>HHM1711E1</b> Kaihanga: TDK Corporation Whakaahuatanga: BALUN 2.3GHZ-2.7GHZ 50/100 0603 I roto i te taonga: 796296 pcs</p> <p><b>RFQ</b></p>	<p><b>HHM1711Q1</b> Kaihanga: TDK Corporation Whakaahuatanga: BALUN 2.3GHZ-3.8GHZ 50/100 0603 I roto i te taonga: 836875 pcs</p> <p><b>RFQ</b></p>
<p><b>HHM17125D1</b> Kaihanga: TDK Corporation Whakaahuatanga: BALUN 2.4GHZ-2.5GHZ 50/50 0603 I roto i te taonga: 496156 pcs</p> <p><b>RFQ</b></p>	<p><b>HHM1710D1</b> Kaihanga: TDK Corporation Whakaahuatanga: BALUN 2.4GHZ-2.5GHZ 50/50 0603 I roto i te taonga: 460907 pcs</p> <p><b>RFQ</b></p>
<p><b>HHM1589B1</b> Kaihanga: TDK Corporation Whakaahuatanga: BALUN 470MHZ-710MHZ 6SMD I roto i te taonga: 234016 pcs</p> <p><b>RFQ</b></p>	<p><b>HHM1603A1</b> Kaihanga: TDK Corporation Whakaahuatanga: BALUN 2.3GHZ-2.7GHZ 50/100 4SMD I roto i te taonga: 120843 pcs</p> <p><b>RFQ</b></p>