

N/A

### DGS35-5HM01024

Tau Wae:	DGS35-5HM01024
Kaihanga / Waitohu:	N/A
Whakaahuatanga hua	ROTARY ENCODR INCREMENT 1024PPR
Ngā Rauemi:	
Waehere Stock	234 pcs stock
Tuhinga mai i	Hong Kong
Te Ara Tuhi	DHL/Fedex/TNT/UPS/EMS

**TONO MO TE WHAKAHUA**

Ko te whakaahua he tohu. Tirohia nga korero mo nga taipitopito hua.

#### Ngā whakaaturanga o DGS35-5HM01024

TAU WAE	DGS35-5HM01024
KAIHANGA	N/A
WHAKAAHUATANGA	ROTARY ENCODR INCREMENT 1024PPR
WHAKAHAERE TOKO WHAKAHAERE / ROHS TŪNGA	
HE RAHINGA KEI TE WĀTEA	234 pcs
PEPA RARAUNGA	
TUHINGA O MUA	8 V ~ 24 V
KĀHUA WHAKAMUTUNGA	Cable
RAUPAPA	-
KO TE ROTATIONAL LIFE (CYCLES MIN)	-
PULSES IA REVOLUTION	1024
MOMO PUTANGA	-
ĒTAHI INGOA	1049306
WHAKATAKOTORANGA	User Selectable
MOMO TAE	Chassis Mount
MOMO KUPUTUHI	Incremental
TUHINGA	No
HANGAIA KI TE WHAKAWHITI	No
MOMO KAIHOKO	Hole for Shaft

#### Ngā tūtohu e hāngai ana

DGS35-5HM01024	DGS35-5HM01024 Kaiwhiwhi	DGS35-5HM01024 Kaiwhakarato
DGS35-5HM01024 Utu	DGS35-5HM01024 Pikitia	DGS35-5HM01024 Whakaahua
DGS35-5HM01024 PDF Datasheet	DGS35-5HM01024 Download Datasheet	Tuhinga DGS35-5HM01024
DGS35-5HM01024 Stock	Hokona DGS35-5HM01024	Hokona DGS35-5HM01024
DGS35-5HM01024	Kaiwhakarato	Kaiwhiwhi

#### Ngā Hua e hāngai ana

	<p><b>DGS35-5HL04096</b></p> <p>Kaihanga: N/A Whakaahuatanga: ROTARY ENCODR INCREMENT 4096PPR I roto i te taonga: 185 pcs</p> <p><b>RFQ</b></p>		<p><b>DGS35-5HN00360</b></p> <p>Kaihanga: N/A Whakaahuatanga: ROTARY ENCODR INCREMENTAL 360PPR I roto i te taonga: 204 pcs</p> <p><b>RFQ</b></p>
	<p><b>DGS35-5J400600</b></p> <p>Kaihanga: N/A Whakaahuatanga: ROTARY ENCODR INCREMENTAL 600PPR I roto i te taonga: 225 pcs</p> <p><b>RFQ</b></p>		<p><b>DGS35-5HN08192</b></p> <p>Kaihanga: N/A Whakaahuatanga: ROTARY ENCODR INCREMENT 8192PPR I roto i te taonga: 148 pcs</p> <p><b>RFQ</b></p>
	<p><b>DGS35-5H202048</b></p> <p>Kaihanga: N/A Whakaahuatanga: ROTARY ENCODR INCREMENT 2048PPR I roto i te taonga: 182 pcs</p> <p><b>RFQ</b></p>		<p><b>DGS35-4L201024</b></p> <p>Kaihanga: N/A Whakaahuatanga: ROTARY ENCODR INCREMENT 1024PPR I roto i te taonga: 199 pcs</p> <p><b>RFQ</b></p>
	<p><b>DGS35-5HL00120</b></p> <p>Kaihanga: N/A Whakaahuatanga: ROTARY ENCODR INCREMENTAL 120PPR I roto i te taonga: 191 pcs</p> <p><b>RFQ</b></p>		<p><b>DGS35-5HM02048</b></p> <p>Kaihanga: N/A Whakaahuatanga: ROTARY ENCODR INCREMENT 2048PPR I roto i te taonga: 175 pcs</p> <p><b>RFQ</b></p>
	<p><b>DGS35-5J405000</b></p> <p>Kaihanga: N/A Whakaahuatanga: ROTARY ENCODR INCREMENT 5000PPR I roto i te taonga: 182 pcs</p> <p><b>RFQ</b></p>		<p><b>DGS35-4LK08192</b></p> <p>Kaihanga: N/A Whakaahuatanga: ROTARY ENCODR INCREMENT 8192PPR I roto i te taonga: 174 pcs</p> <p><b>RFQ</b></p>
	<p><b>DGS35-5J404096</b></p> <p>Kaihanga: N/A Whakaahuatanga: ROTARY ENCODR INCREMENT 4096PPR I roto i te taonga: 176 pcs</p> <p><b>RFQ</b></p>		<p><b>DGS35-4LN10000</b></p> <p>Kaihanga: N/A Whakaahuatanga: ROTARY ENCODR INCREMENT 10000PPR I roto i te taonga: 141 pcs</p> <p><b>RFQ</b></p>