





AVX Corporation


CP0603A1441CWTR

Tau Wae:	CP0603A1441CWTR
Kaihanga / Waitohu:	AVX Corporation
Whakaahuatanga hua	RF DIR COUPL 1.429-1.453GHZ 0603
Ngā Rauemi:	 CP0603A1441CWTR.pdf
RoHS Tūnga	 Kei roto nga rangatira / RoHS kaore i te ture
Waehere Stock	430782 pcs stock
Tuhinga mai i	Hong Kong
Te Ara Tuhi	DHL/Fedex/TNT/UPS/EMS

TONO MO TE WHAKAHUA

Ko te whakaahua he tohu. Tirohia nga korero mo nga taipitopito hua.



Ngā whakaaturanga o CP0603A1441CWTR

TAU WAE	CP0603A1441CWTR
KAIHANGA	AVX Corporation
WHAKAAHUATANGA	RF DIR COUPL 1.429-1.453GHZ 0603
WHAKAHAERE TOKO WHAKAHAERE / ROHS TŪNGA	Kei roto nga rangatira / RoHS kaore i te ture
HE RAHINGA KEI TE WĀTEA	430782 pcs
PEPA RARAUNGA	 CP0603A1441CWTR.pdf
PŪRERE PŪRERE WHAKARATO	0603
RAUPAPA	-
HOKI HOKI	-
MANA - MAX	3W
PACKAGING	Tape & Reel (TR)
PAA / CASE	0603 (1608 Metric)
TAUMATA WHAKAARO MOE (MSL)	1 (Unlimited)
WHAKAHAERE TOKO WHAKAHAERE / ROHS TŪNGA	Contains lead / RoHS non-compliant
WHAKAMOTU	-24dB
TE HAINATANGA WHAKATAUNGA	0.4dB
RAUTANGA	1.429GHz ~ 1.453GHz
WHAKAAHUATANGA TAIPITOPITO	RF Directional Coupler PDC 1.429GHz ~ 1.453GHz 16.5 ± 1db 3W 0603 (1608 Metric)
HONONGA TAE	16.5 ± 1db
HE MOMO HOAHOA	Standard
NGA TONO	PDC

Ngā tūtohu e hāngai ana

AVX Corporation CP0603A1441CWTR	CP0603A1441CWTR Kaihiwhi	CP0603A1441CWTR Kaiwhakarato
CP0603A1441CWTR Utu	CP0603A1441CWTR Pikitia	CP0603A1441CWTR Whakaahua
CP0603A1441CWTR PDF Datasheet	CP0603A1441CWTR Download Datasheet	Tuhinga CP0603A1441CWTR
CP0603A1441CWTR Stock	Hokona CP0603A1441CWTR	Hokona AVX Corporation CP0603A1441CWTR
AVX Corporation CP0603A1441CWTR	AVX Corporation Kaiwhakarato	AVX Corporation Kaihiwhi
AVX Corporation CP0603A1441CWTR	AVX Corporation [MIL] CP0603A1441CWTR	

Ngā Hua e hāngai ana

 <p>CP0603A1441CLTR Kaihanga: AVX Corporation Whakaahuatanga: RF DIR COUPL 1.429-1.453GHZ 0603 I roto i te taonga: 443897 pcs</p> <p>RFQ</p>	 <p>CP0603A1180BLTR Kaihanga: AVX Corporation Whakaahuatanga: RF DIR COUPLER 1.18GHZ 0603 I roto i te taonga: 481317 pcs</p> <p>RFQ</p>
 <p>CP0603A1747CLTR Kaihanga: AVX Corporation Whakaahuatanga: RF DIR COUPLR 1.71-1.785GHZ 0603 I roto i te taonga: 448804 pcs</p> <p>RFQ</p>	 <p>CP0603A1550AWTR Kaihanga: AVX Corporation Whakaahuatanga: RF DIR COUPLER 1.55GHZ 0603 I roto i te taonga: 345160 pcs</p> <p>RFQ</p>
 <p>CP0603A1747BWTR Kaihanga: AVX Corporation Whakaahuatanga: RF DIR COUPLR 1.71-1.785GHZ 0603 I roto i te taonga: 458605 pcs</p> <p>RFQ</p>	 <p>CP0603A1441DWTR Kaihanga: AVX Corporation Whakaahuatanga: RF DIR COUPL 1.429-1.453GHZ 0603 I roto i te taonga: 372349 pcs</p> <p>RFQ</p>
 <p>CP0603A1575DWTR Kaihanga: AVX Corporation Whakaahuatanga: RF DIR COUPLER 1.575GHZ 0603 I roto i te taonga: 370445 pcs</p> <p>RFQ</p>	 <p>CP0603A1441AWTR Kaihanga: AVX Corporation Whakaahuatanga: RF DIR COUPL 1.429-1.453GHZ 0603 I roto i te taonga: 401231 pcs</p> <p>RFQ</p>
 <p>CP0603A0976CLTR Kaihanga: AVX Corporation Whakaahuatanga: RF DIR COUPLER 976MHZ 0603 I roto i te taonga: 438335 pcs</p> <p>RFQ</p>	 <p>CP0603A1441BWTR Kaihanga: AVX Corporation Whakaahuatanga: RF DIR COUPL 1.429-1.453GHZ 0603 I roto i te taonga: 353618 pcs</p> <p>RFQ</p>
 <p>CP0603A1600CWTR Kaihanga: AVX Corporation Whakaahuatanga: RF DIR COUPLER 1.6GHZ 0603 I roto i te taonga: 381924 pcs</p> <p>RFQ</p>	 <p>CP0603A0991DWTR Kaihanga: AVX Corporation Whakaahuatanga: RF DIR COUPLER 991MHZ 0603 I roto i te taonga: 445592 pcs</p> <p>RFQ</p>