



1575AT54A0010E

Tau Wae: 1575AT54A0010E
 Kaihanga / Waitohu: Johanson Technology
 Whakaahuatanga hua: RF ANT 1.575GHZ/1.602GHZ CHIP
 Ngā Rauemi: 1575AT54A0010E.pdf
 RoHS Tūnga: Whakahaerehia te kore utu / RoHS
 Waehere Stock: 51928 pcs stock
 Tuhinga mai i: Hong Kong
 Te Ara Tuhi: DHL/Fedex/TNT/UPS/EMS

TONO MO TE WHAKAHUA

Ko te whakaahua he tohu. Tirohia nga korero mo nga taipitopito hua.

Ngā whakaaturanga o 1575AT54A0010E

TAU WAE	1575AT54A0010E
KAIHANGA	Johanson Technology
WHAKAAHUATANGA	RF ANT 1.575GHZ/1.602GHZ CHIP
WHAKAHAERE TOKO WHAKAHAERE / ROHS TŪNGA	Whakahaerehia te kore utu / RoHS
HE RAHINGA KEI TE WĀTEA	51928 pcs
PEPA RARAUNGA	1575AT54A0010E.pdf
VSWR	-
WHAKAMUTUNGA	Solder
RAUPAPA	-
HOKI HOKI	-9.5dB
MANA - MAX	2W
PACKAGING	Tape & Reel (TR)
ĒTAHI INGOA	712-1571-2
TUHINGA O MUA	2
MOMO TAE	Surface Mount
TAUMATA WHAKAARO MOE (MSL)	1 (Unlimited)
WHAKAHAERE TOKO WHAKAHAERE / ROHS TŪNGA	Lead free / RoHS Compliant
TIAKI INGOA	-
TEITEI (MAX)	0.126" (3.20mm)
HUA	1.3dBi
MAHINGA RAWE	1.575GHz ~ 1.605GHz
RANGAHAU RŌPŪ	UHF (1 GHz ~ 2 GHz)
TAUTANGA (POARI / PAE)	1.575GHz, 1.602GHz
NGĀ ĀHUATANGA	-
WHAKAAHUATANGA TAIPITOPITO	1.575GHz, 1.602GHz GLONASS, GPS Chip RF Antenna 1.575GHz ~ 1.605GHz 1.3dBi Solder Surface Mount
NGA TONO	GLONASS, GPS
MOMO ANTENNA	Chip

Ngā tūtohu e hāngai ana

Johanson Technology 1575AT54A0010E	1575AT54A0010E Kaiwhiwhi	1575AT54A0010E Kaiwhakarato
1575AT54A0010E Utu	1575AT54A0010E Pikitia	1575AT54A0010E Whakaahua
1575AT54A0010E PDF Datasheet	1575AT54A0010E Download Datasheet	Tuhinga 1575AT54A0010E
1575AT54A0010E Stock	Hokona 1575AT54A0010E	Hokona Johanson Technology 1575AT54A0010E
Johanson Technology 1575AT54A0010E	Johanson Technology Kaiwhakarato	Johanson Technology Kaiwhiwhi
Johanson Technology 1575AT54A0010E	Johanson 1575AT54A0010E	Johanson Technology Inc. 1575AT54A0010E

Ngā Hua e hāngai ana

<p>15762B200 Kaihanga: Agastat Relays / TE Connectivity Whakaahuatanga: RELAY GEN PURP I roto i te taonga: 4045 pcs</p> <p>RFQ</p>	<p>1576460000 Kaihanga: Weidmuller Whakaahuatanga: FOOT SNAP-ON TS32 TS35 ORANGE I roto i te taonga: 34727 pcs</p> <p>RFQ</p>
<p>1575990 Kaihanga: Phoenix Contact Whakaahuatanga: CABLE 8POS I roto i te taonga: 734 pcs</p> <p>RFQ</p>	<p>1575CH15A0030E Kaihanga: Johanson Technology Whakaahuatanga: IC RF SPLITTER I roto i te taonga: 133461 pcs</p> <p>RFQ</p>
<p>1576320000 Kaihanga: Weidmuller Whakaahuatanga: CONN BASE BOTTOM ENTRY SZ10 I roto i te taonga: 6831 pcs</p> <p>RFQ</p>	<p>1575AT47A0040 Kaihanga: Johanson Technology Whakaahuatanga: RF ANT 1.575GHZ CHIP SOLDER SMD I roto i te taonga: 4299 pcs</p> <p>RFQ</p>
<p>1575AM55B0001E Kaihanga: Johanson Technology Whakaahuatanga: RF ANT 1.575GHZ CHIP SOLDER SMD I roto i te taonga: 6086 pcs</p> <p>RFQ</p>	<p>1576009 Kaihanga: Phoenix Contact Whakaahuatanga: CABLE 8POS I roto i te taonga: 1471 pcs</p> <p>RFQ</p>
<p>15762A2L1 Kaihanga: Agastat Relays / TE Connectivity Whakaahuatanga: RELAY GEN PURP I roto i te taonga: 4485 pcs</p> <p>RFQ</p>	<p>1575AT43A0040E Kaihanga: Johanson Technology Whakaahuatanga: RF ANT 1.561GHZ/1.575GHZ CHIP I roto i te taonga: 109670 pcs</p> <p>RFQ</p>
<p>1575AM55A0001 Kaihanga: Johanson Technology Whakaahuatanga: RF ANT 1.575GHZ CHIP SOLDER SMD I roto i te taonga: 2920 pcs</p> <p>RFQ</p>	<p>1575AT44A0010E Kaihanga: Johanson Technology Whakaahuatanga: RF ANT 1.575GHZ CHIP SOLDER SMD I roto i te taonga: 3173 pcs</p> <p>RFQ</p>